

Upgrades available

(Installation included only with Annual service)

Complete Prism head Assembly with/PCBS no hud/Handset	\$3,274.00
- This is what it costs to replace a completely flooded head {Labor Included}	
- Complete new head with current upgrades, Dive CAN only	
Adapter, Hose, ea (part that screws into the head)	\$4.00
Elbows Pair (FMCL)	\$36.00
Solenoid supply hose	\$30.95
LPQD Inflator hoses (o2Mav, MAV, ADV, BCD)	\$42.00
LP Hose 30" (BMCL ONLY)	\$30.95
BOV hose (42")	\$62.95
BOV Kit	\$672.95
LP Swivel (Required for BOV Kit on 5 port DIL first stage)	\$34.95
New Sensor Holders	\$22.00
Upgrade to Petrel 3 (\$500 credit offered for Petrel 2 trade in, Limited time)	\$2,259.95
Transmitter for Petrel 3 - Yellow	\$399.95
Transmitter for Petrel 3 - Grey	\$399.95
Lower Strap, (pair) Counterlung, FMCL	\$29.95
Standard Yoke. FMCL Only	\$40.00
Long Yoke FMCL Only	\$40.00
Side Strap, (pair) Counterlung, FMCL	\$11.95
FMCLs (stripped) Pair	\$322.00
Small FMCLs (stripped) Pair	\$569.95
Inhalation Counter Lung Assembly, extra port (stripped)	\$284.95
New Corrogated Hoses (FOUR) FMCL 14"	\$95.00
New Corrogated Hoses (four) BMCL 2x11" 2x16	\$101.80
One each, OPR valves on first stages	\$23.95
Strain Relief Upgrade (pair)	\$80.00
Stainless Steel Battery Cover Upgrade	\$210.00
Stainless Steel H- Plate Upgrade	\$279.95
Upgrade Diluent to a 7port Body	\$240.00
BMCL upgrade from FMCL	\$1,345.95
Upgrade Oxygen MAV (FMCL)	\$155.95
Bucket (requires old hardware)	\$342.00
Complete bucket assembly with band and latches	\$659.95
New Bucket hardware (band Assy.)	\$282.00
Replacement Oteiker Clamps (each)	\$4.00
Replacement Bucket clamps (each)	\$56.00
Replacement Bucket latch keeper	\$46.00
Replacement Latch, Battery cover	\$18.00
Cover Rebuild (requires old cover and hardware)	\$90.00
Replacement Prism 2 Cover	\$140.00
Replacement Scrubber Basket and Cap Assembly	\$517.95